CHAMUNDESWARI ELECTRICITY SUPPLY CORPORATION LIMITED Sheduled Outage Information							
Details of Power Shut Down due to maintenance of Distribution System							
S1. No.	Date of Outage	Name of Town	Name of Sub- Station	Name of Feeder	Area Affected	From (HH:MM)	To (HH:MM)
1		Madiker	66/11 Madikeri	F3 Gaddige	A.V School, Gaddige, Mahadevapete, Market convent Junction, S.P Office	10:00	17:00
2	10.03.2021	Mysore	66/11 KV Dattagalli	Rajarajeswari	BEML LAYOUT, RAJARAJESWARINAGARA, KAJJANE BADAVANE, RT NAGARA, KERGALLI, RAMANAHUNDI, BADAGALAHUNDI, NANJARAJANAHUNDI AND SURROUNDING AREA.		