

CHAMUNDESHWARI ELECTRICITY SUPPLY CORPORATION LIMITED

Sheduled Outage Information

Details of Power Shut Down due to maintenance of Distribution System

Si.No.	Date of Outage	Name of Sub-div	Name of Sub-Station	Name of Feeder	Area Affected	From (HH:MM)	To (HH:MM)
1	10.08.2020	Bannuru	66/11KV Thumbla	N.G.Hundi, Muthathi, Hittuvally, Kupya gate.	Thumbla, Kupya, Hosakote under village panchayath.	10:00	17:00
2		Bannuru	66/11KV Chidravally	Arebommanahally, Konagahally, Mallikarjuna, S.Doddapura, Naripura, Ramegowdanapura, Muneshwara.	Chidravally, Ukkalagere, Somanathapura under village panchayath.		
3		T.Narasipura	66/11KV Vyasaraajapura	Vyasaraajapura, Horalahally, Kaggaluru.	Sosale, Benakanahally, Kolathuru, Doddebagilu, Ukkalagere, R.P.hundi, under village panchayath.		
4		T.Narasipura	66/11KV Gargeshwari	Yadahalli, Thirumakudalu, Hosakempainahundi, Induvalu	Yadadore, Kurisiddanahundi, Gargeshwari, Halethirumakudalu, Induvalu, Rayarahundi, Hosakempainahundi, Halekempainahundi under village panchayath.		