Scheduled Outage Information

Details of power Shut Down due to Maintenance of Distribution System from DDMMYY to DDMMYY

| SI. No | Date of outage | Name of Town | Name of Power House (Sub- Station) | Name of Feeder | Area Affected | From (HH:MM) | To (HH:MM) |
|-----------|----------------|-----------------|---------------------------------------|---|--|-----------------|---------------|
| 1 | 13-12-2020 | Santhemarahally | 66/11 KV Muss Santhemarahally | Honnuru, Santhemarahally, Naviluru, Alduru, Mangla W/S, Kuderu, Kempanapura, Duggati, Amble, Avitha Green Solar, Ummaturu W/S, Chungadipura | Honnuru, Santhemarahally, Naviluru, Alduru, Mangla W/S, Kuderu, Kempanapura, Duggati, Amble, Avitha Green Solar, Ummaturu W/S, Chungadipura in Surrounding Area | 10:00 | 17:00 |