## CHAMUNDESWARI ELECTRICITY SUPPLY CORPORATION LIMITED

## **Sheduled Outage Information**

## Details of Power Shut Down due to maintenance of Distribution System

S1. No	Date of Outage	Name of Town	Name of Sub-Station	Name of Feeder	Area Affected	From (HH:MM)	To (HH:MM)
1	14.08.2020	N.R.Mohalla Division.	66/11 KV DK MUSS	Agrahara, Marigudi, Palace, JC Feeder, Mall of Mysuru, Ramanuja, Siddartha, Maharaja, Bhuvaneshwari, Ramavilas, New Suttur, Garuda Mall	Ramanuja road, Hosabandikeri, JSS hospital, Basaveshwara road, Chamundipuram surrounding, Sub Urbn Bus Stand, Nazarbad, Ittigegudu, Zoo surrounding, Govt., Guest House surrounding, Talluku Office, Urs Road, BN Road, Chamundi Hill, Siddarthanagara, Alanahalli surrounding, Giridarshini layout, Palace surrounding, Sri Harsha Road, Sayyajirao Road, Irvin Road, Ashoka Road, Garadi kere, Uma Talkies road, Kumbarageri, Behind SBI, Hallada keri, Dhanwantari Road, Shivaram Pete surrounding.	10:00	17:00