## **CHAMUNDESHWARI ELECTRICITY SUPPLY CORPORATION LIMITED**

## **Sheduled Outage Information**

## Details of Power Shut Down due to maintenance of Distribution System

Si.No.	Date of Outage	Name of Sub-div	Name of Sub- Station	Name of Feeder	Area Affected	From ( HH:MM)	To ( HH:MM)
1	16.08.2020	Mandya Sub Division	66/11KV Mandya	Hoshalli	Karasavadi road, BVK LAYOUT, Ambujamma park, KHB colony, Bisilumaramma circle, Bevinakatte	09:00	17:00