

CHAMUNDESWARI ELECTRICITY SUPPLY CORPORATION LIMITED

Sheduled Outage Information

Details of Power Shut Down due to maintenance of Distribution System

Sl.No.	Date of Outage	Name of Town	Name of Sub-Station	Name of Feeder	Area Affected	From (HH:MM)	To (HH:MM)
1	17.12.2020	N.R.Mohalla Division.	66/11 KV Megalapura MUSS	B N Halli, Kuppegala, Siddaramanahundi, Duddagere, Megalapura, Hosahalli, Industrial	Megalapura, Keelanapura, Siddaramanahundi, MC Hundi, Innam Uttanahalli, Kuppegala, Muddegowdanahundi, Ranganathapura, Srinivasapura, Devegowdanahundi, Yadakola, Kadavekattahundi, Hosahalli, Gurukarapura, Duddagere, Mahadevicolony, Lakshmipura, Madavagere, Varakodu, Kupya, Bommanayakanahalli, KP Hundi	10:00	17:00