CHAMUNDESWARI ELECTRICITY SUPPLY CORPORATION LIMITED Sheduled Outage Information Details of Power Shut Down due to maintenance of Distribution System							
62	19.12.2023	N.R.Mohalla Division	66/11 KV DK Maidhana MUSS	Agrahara	Ramanuja road, Hosabandikeri, JSS hospital, Basaveshwara road, Chamundipuram surrounding, Sub Urbn Bus Stand, Nazarbad, Ittigegudu, Zoo surrounding, Govt., Guest House surrounding, Talluku Office, Urs Road, BN Road, Chamundi Hill, Siddarthanagara, Alanahalli surrounding, Giridarshini layout, Palace surrounding, Sri Harsha Road, Sayyajirao Road, Irvin Road, Ashoka Road, Garadi kere, Uma Talkies road, Kumbarageri, Behind SBI, Hallada keri, Dhanwantari Road, Shivaram Pete surrounding.	10:00	17:30
63				Marigudi			
64				Palace			
65				JC Feeder			
66				Mall of Mysuru			
67				Ramanuja			
68				Siddartha			
69				Maharaja			
70				Bhuvaneshwari			
71				Ramavilas			
72				New Suttur			
73				Garuda Mall			