CHAMUNDESHWARI ELECTRICITY SUPPLY CORPORATION LIMITED

Sheduled Outage Information

Details of Power Shut Down due to maintenance of Distribution System

Si.No.	Date of Outage	Name of Sub-div	Name of Sub- Station	Name of Feeder	Area Affected	From (HH:MM)	To (HH:MM)
1	20.08.2020	Nanjangud-02	66/11KV Chandravadi	Basapura, Rajuru, Kappasoge, Tharaganahalli	Nellithalapura, Kurihundi, Haradanahally, Duggally under village panchayath.		17:00
2			66/11KV Hemmaragala	Hemmaragala, Madrally, Nerale, srinagara.	Hemmaragala, Kumbrally,Madrally, Srinagara, Singaripura, Gonathagala, Hedathale, Bhujangaiahnahundi, mallahally, Hampapura, Halepura under village panchayath.		