

CHAMUNDESHWARI ELECTRICITY SUPPLY CORPORATION LIMITED

Sheduled Outage Information

Details of Power Shut Down due to maintenance of Distribution System

Si.No.	Date of Outage	Name of Sub-div	Name of Sub-Station	Name of Feeder	Area Affected	From (HH:MM)	To (HH:MM)
1	20.11.2020	Bannuru	66/11KV Bannuru	Bannuru 1&2, Beedanahally, Chandally, Kirugavalu, Kodagally, M.P.Mill, Chamundeshwari, Kethupura, rangasamudra, B C Hally, Hegguru, Bugathagally	Bannuru Town, Kodagally, B Seehally, Hegguru, Athally, Kethupura, Rangasamudra Under Village Panchayath	10:00	17:00
2			66/11KV Maliyuru	SPR Industrial, Basavanahally, Bettahally, Nanjapura	Chidrahally & Doddabagilu Under Village Panchayath		
3		Mysore	220/66/11 KV R.K.Nagara	GANGOTHRI	Sahukaar Chennaiah Road, Sarasvathipuram Police Quarters Road, Police Station Road, Maruthi Temple Road And Sorrounding Areas.		
4		Mysore	220/66/11 KV R.K.Nagara	KUVEMPU	KUKKARAHALLI,SARASWATHIPURAM 12TH Main to 17th Main, MARUTHI TEMPLE ROAD, VISHVAMANAVA DOUBLE ROAD, LIBRARY, KAMAKSHI HOSPITAL AND SORROUNDING AREAS.		