CHAMUNDESHWARI ELECTRICITY SUPPLY CORPORATION LIMITED

Sheduled Outage Information

Details of Power Shut Down due to maintenance of Distribution System

Sl.No.	Date of Outage	Name of Sub-div	Name of Sub- Station	Name of Feeder	Area Affected	From (HH:MM)	To (HH:MM)
1	21.02.2024	Nanjanagudu-02	66/11KV Chandravadi	Rajuru, Kappasoge, Tharaganahally.	Nellithalapura, kurihundi, Haradanahally & Duggally under village Panchayath Area.	- 10.00AM	5.00PM
2		Nanjanagudu-02	66/11KV Hura	F1-Hallare,F2-Malkundi,F4-Channapattana,F5-Hadya,F3- Hanchipura,F6-Yediyala,F7-Kadajetti,Madapura W/S.	Hura, Hadya, Hallare, Devarayashettipura & Hediyala under village Panchayath Area.		