CHAMUNDESHWARI ELECTRICITY SUPPLY CORPORATION LIMITED

Sheduled Outage Information

Details of Power Shut Down due to maintenance of Distribution System

SI.No.	Date of Outage	Name of Sub-div	Name of Sub- Station	Name of Feeder	Area Affected	From (HH:MM)	To (HH:MM)
1	23.11.2023	Nanjanagudu-02	66/11KV Karya	Karepura, Chinnambally, Banuru, Hanumanapura.	Hadya, Kaahally, Kamally, Karya, aralikatte, Banuru, Chinnambally, Chunchanahally, Hanumanapura, Kakkarahatti, Bhogayyanahundi under village Panchayath Area.	7.00AM	6.00PM
2		Gundlupete	66/11KV Terakanambhi	Bommanahalli, Kundakere, Katnawadi, Depapura NJY, Govindapura, Kaggala, Kelsipura, Lakkuru, Factory Water supply.	Bommanahalli, Kundakere, Katnawadi, Depapura NJY, Govindapura, Kaggala, Kelsipura, Lakkuru, Factory Water supply in surrounding places.	9.00AM	5.00PM