## CHAMUNDESHWARI ELECTRICITY SUPPLY CORPORATION LIMITED

Sheduled Outage Information

## Details of Power Shut Down due to maintenance of Distribution System

Si.No.	Date of Outage	Name of Sub-div	Name of Sub- Station	Name of Feeder	Area Affected	From ( HH:MM)	To ( HH:MM)
1	24.06.2020	Kothathi Sub Division	66/11KV V.C.FARM	V.C.Farm, Holalu, Mallenahalli, Shivalli, Hulikere	V.C.Farm, Holalu, Mallenahalli, Shivalli, Hulikere, B. Hatna, Gunnayakanahalli , Hullenahalli, Chandgalu Bevakallu, Dudda	09:00	17:00