CHAMUNDESHWARI ELECTRICITY SUPPLY CORPORATION LIMITED

Sheduled Outage Information

Details of Power Shut Down due to maintenance of Distribution System

SI.No.	Date of Outage	Name of Sub-div	Name of Sub- Station	Name of Feeder	Area Affected	From (HH:MM)	То (нн:мм)
1	25.02.2023	Nanjanagudu-01	66/11KV Maradihundi	Nandagundapura, Thumanerale, Maradihundi & Kurattikaval	Thumnerale & Hosakote under village Panchayath Areas.	8.00AM	6.00PM