

CHAMUNDESWARI ELECTRICITY SUPPLY CORPORATION LIMITED

Sheduled Outage Information

Details of Power Shut Down due to maintenance of Distribution System

Sl.No.	Date of Outage	Name of Town	Name of Sub-Station	Name of Feeder	Area Affected	From (HH:MM)	To (HH:MM)
1	25.11.2020	N.R.Mohalla Division.	66/11 KV Vajamangala MUSS	Mellahally, Varakodu, Vajamangala, Vidya Vikas, Mayabandhar, Police Layout, K G Hundi, Harohalli	Mellahalli, Harohalli, Hallikerehundi, Shivapura, Halagaiahnahundi, Pillahalli, Varakodu, Badagalahundi, Moodalahundi, K.P. Hundi, Varuna, Dandikere, Vajamangala, Badagalahundi, Mosambayanahundi, Yandalli, Sajjehundi, Mahadeshwara layout, Chikkahalli, Choranahalli, Nadanahalli, Nethajinagara, JSS Layout, Vasanthanagara, Sukadayinagara, Saptamatruke layout, Prakruti Layout	10:00	17:00
2		N.R.Mohalla Division.	66/11 KV Megalapura MUSS	B N Halli, Kuppegala, Hosahalli, Industrial, Megalapura, Siddaramanahundi	Megalapura, Keelanapura, Siddaramanahundi, MC Hundi, Innam Uttanahalli, Kuppegala, Muddegowdanahundi, Ranganathapura, Srinivasapura, Devegowdanahundi, Yadakola, Kadavekattehundi, Hosahalli, Gurukarapura, Duddagere, Mahadevicolony, Lakshmipura, Madavagere, Varakodu, Kupya, Bommanayakanahalli, KP Hundi	10:00	17:00