CHAMUNDESWARI ELECTRICITY SUPPLY CORPORATION LIMITED

Sheduled Outage Information

Details of Power Shut Down due to maintenance of Distribution System

S1. No	Date of Outage	Name of Town	Name of Sub-Station	Name of Feeder	Area Affected	From (HH:MM)	To (HH:MM)
1	25.06.2020	N.R.Mohalla Division.	66/11 KV DK Maidhana MUSS	Siddartha	Siddarthanagara, Kurubarahalli, Vinayamarga, Buddamrga, Zoo, Race Course.	10:00	17:00