## **CHAMUNDESHWARI ELECTRICITY SUPPLY CORPORATION LIMITED**

## **Sheduled Outage Information**

## Details of Power Shut Down due to maintenance of Distribution System

SI.No.	Date of Outage	Name of Sub-div	Name of Sub- Station	Name of Feeder	Area Affected	From ( HH:MM)	To ( HH:MM)
1	26.11.2021	Bannuru	66/11KV Maliyuru	SPR Industries, Basavanahally, Bettahally, Nanjapura.	Chidravalli & Doddabagilu under village Panchayath Area.	8:00	16:00
2	27.11.2021					9:00	16:00