CHAMUNDESWARI ELECTRICITY SUPPLY CORPORATION LIMITED

Sheduled Outage Information

Details of Power Shut Down due to maintenance of Distribution System

S1. No	Date of Outage	Name of Town	Name of Sub-Station	Name of Feeder	Area Affected	From (HH:MM)	To (HH:MM)
1	26.08.2020	N.R.Mohalla Division.	66/11 KV Devanuru (Mysuru) MUSS	Ramnahalli Melapura Sathagally Neharu Nagara Hanchya Bharath Nagar Rajivanagar Shakthi Huliyamma Radhakrishna Manasinagara K.S.R.T.C.Depo	Rajeevnagara 1st, 2nd and 3rd stage, Shanthinagara, Neharunagar, Radhakrishnanagara, Bharathnagara, JSS Layout, Gousiyanagara, Shakthinagara, Kyathamaranahalli, Hanchya, Kalyanagiri, Bugathagalli, Melapura, Rammanahalli Water Works, Kalasiddanahundi, Sathagalli, Rammanahalli, Bannuru Ring Road.	10:00	17:00
2	26.08.2020	Nanjanagudu-02	66/11KV Karya	Karepura, Chinnambally, Banuru, Hanumanapura.	Hadya, Kaahally, Kamally, Karya, Aralikattehundi, Banuru, Chinnambally, Chunchanahally, Hanumanapura, Kakkarahatti, Bhogainahundi under village panchayath.	10.00AM	5.00PM