

CHAMUNDESHWARI ELECTRICITY SUPPLY CORPORATION LIMITED

Sheduled Outage Information

Details of Power Shut Down due to maintenance of Distribution System

Si.No.	Date of Outage	Name of Sub-div	Name of Sub-Station	Name of Feeder	Area Affected	From (HH:MM)	To (HH:MM)
1	27.08.2020	Mandya Sub Division	66/11KV Mandya	Hoshalli	Karasavadi road, BVK LAYOUT, Ambujamma park, KHB colony, Bisilumaramma circle, Bevinakatte	09.00 AM	5.00PM
2	27.08.2020	Nanjanagudu-01	66/11KV Maradihundi	Nandagundapura, Thumanerale, Maradihundi, Kurattikaval	Thumanerale, Hosakote under village panchayath.	10.00AM	5.00PM